

March 21, 2017

To whom it may concern,

This document verifies the test results of Polylok's trench drain and grate part no. PL-90860-G. A six inch test section of trench drain and grate was placed in a vessel of 200F deg. water. The test sample was subjected to 30 minutes at 200F deg. temperature. The test sample was removed from the vessel and immediately tested. A reduction of 5% of ambient load strength was recorded.

Should you have any questions or require clarification, please do not hesitate to contact me.

Yours sincerely,

Charles Brix Vice President Design & Development

T: (203) 626-6123 F: (203) 284-3495 www.polylok.com